

**Environmental Health & Sanitation Chemicals** 

CHEMICAL CORPORATION

# Technical Data





DIRECTIONS FOR USE

Solar Burst was designed to be part

Program. It is the copartner in High

Speed Floor Technology, made easy

by simple instructions that produce

1.) Dust mop floors to remove dirt.

2.) Add 2oz. of Solar Burst per gallon

of water in a clean mop bucket.

phenomenal results. Read label

carefully and follow directions.

**MOP & BURNISH METHOD:** 

of the Solar System Floor Care

## **DESCRIPTION**

Solar Burst Floor Reconditioner was designed for todays propane and other high speed buffers. The use of this product will greatly reduce labor cost and prolong the higher gloss curve of your floors. This space age formulation was made for damp mopping on the floor and then high speed burnishing the floor with either a high speed or propane ultra speed machine for a deep -- high gloss! Can be used in auto scrubbing machines and then followed by high speed burnishing. Solar Burst repairs scuffs, scratches and restores better than new gloss.

Solar Burst cleans and restores your floors to a brilliant shine in one step.

For optimum results, use with the Solar System Floor Program. First apply four or five coats of Solar Gloss Seal & Finish. Clean daily with Solar Clean!

#### Where To Use

- Vinyl
- Rubber
- Terrazzo
- LinoleumSealed Wood
- Asphalt
- Vinyl Asbestos
- Schools
- Super Markets
- Offices
- Hospitals
- Banks
- Nursing Homes
- Municipalities

## **USES / BENEFITS**

- Compatible with most high speed floor finishes.
- Reduces labor cost with one step.
- For propane and all high speed floor equipment.
- Cleans and restores superbly.
- Stops slippery floors.
- Eliminates powdering.
- Repairs scuffs, scratches and restores gloss.

# **PRECAUTIONS**

Keep Out Of Reach Of Children

# 3.) Damp mop floors with solution, uniformly applying a thin coat.

4.) Let floors dry thoroughly. Burnish with high speed floor machine and soft polishing pad.

#### **SPECIFICATIONS**

Buffability	. Very Good to Excellent
	Milky Blue
	20,000+ sq. ft. gal.
Flash Point	None
Fragrance	Lemon
Gloss	Exceptional
pH	7.0 - 8.0

#### **AUTOMATIC SCRUBBER METHOD:**

- 1.) Dust mop floors to remove dirt.
- 2.) Fill scrubber solution tank with water adding Solar Burst at 4oz. per gallon of water.
- 3.) Scrub floors picking up solution as if cleaning. Detail mop any trails that are left from behind machine.
- 4.) Let floors dry thoroughly. Burnish with propane or other high speed floor equipment.

EXCELLENCE SINCE 1964

rs Of NOTTH WOODS Chemicals



**"Exclusive Distributors Of**