

Environmental Health & Sanitation Chemicals

Technical Data

INFINITE SOLAR GLOSS

HIGH PERFORMANCE FLOOR FINISH & SEALER

DESCRIPTION

New Infinite Solar Gloss Expanded Solids, High Speed, Floor Sealer & Finish was specifically formulated as a base for The Solar System Floor Care Program. To allow the highest gloss, plus longevity, plus repairability has long been the goal for the floor finish technician. We have achieved this goal, without a separate product to seal first.

New Infinite Solar Gloss Expanded Solids Floor Sealer & Finish has a high solids content, with a new high density molecular micron that penetrates porous floors and seals and finishes in one operation.

New Infinite Solar Gloss used as the base of The Solar System will be unequaled to anything on the market today, or the near future. Simple fast drying formula, offers the utopia in High Gloss Wet Look, with a simple methodical system to follow.

End users with high speed propane burnishing will love it. This formula allows a far greater number of polymers per square micron of finish so outstanding wear and responsiveness is fantastic. Will not powder, and works equally well on all resilient floors and terrazzo.

USES / BENEFITS

- New Expanded Solids Formula
- High Density Seal & Finish
- Gloss Deepens More With Repeated Burnishing
- High Density Technology
- High Performance
- Reduces need to recoat
- Increases time between strips
- Saves Labor & Product Cost
- Never Discolors
- Fantastic Economy Coverage
- Slip Resistant CSMA / UL

PRECAUTIONS

Keep Out Of Reach Of Children

SPECIFICATIONS

| Color Dried4500 | Crystal Clear |
|--------------------|-----------------|
| Drying Time4300 | 20 -30 minutes |
| Gloss (Gardner) | 1 Coat 84 |
| | 3 Coats 98 Plus |
| Total Solids | |
| pH | 8.2 - 8.7 |
| Leveling | |
| Heel Mark Resistar | |
| Detergent Resistar | |
| Powdering Resistar | ice Excellent |

DIRECTIONS FOR USE

Infinite Solar Gloss High Speed Seal & Finish was designed for total perfection in a High Speed Floor Care Program. Instructions for use and application should be followed explicitly.

- Completely strip all old wax or finish.
- If applying over old finish, be sure that all soils are removed or they will lock in.
- When stripping, make sure all stripping solution has been removed by rinsing - or use North Woods™ Bare Bones!
- Apply finish in a uniform, thin coat and allow to dry 20 - 30 minutes between application times. A minimum of two coats must be applied.
- 5. For routine cleaning, mop or auto scrub with **Solar Clean**.
- Maintain by burnishing with propane or other high speed equipment, with Solar Burst Floor Reconditioner or Solar Shine Buffing Restorer.

SINCE 1964

"Exclusive Distributors Of



Chemicals"

